

Fräserübersicht

Material	HEDmill One	CIMT Pi5
CoCr	T9024	= T1104
CoCr	T9010	= T4205
CoCr	T9007	= T4217
CoCr	T9099	= T4325
CoCr	T9098	= T4005
CoCr	T9006	= T4220
CoCr	T9019	= T4308
CoCr	T9004 / T9021	= T4212 / T4219
CoCr	T9014	= T1099
CoCr	T9003	= T1011
CoCr	T9001	= T1016
CoCr	T9002	= T4218
CoCr	T9026	= T11111
CoCr	T9016	=
CoCr/Titan	T9018 / T4004	= T1002
CoCr/Titan	T9017	= T1001
CoCr/Titan	T9012	= T4003
CoCr/Titan	T9025	= T4020
CoCr/Titan	T9009	=
Kunststoff	T3060	= T1060
Kunststoff	T3010	= T1010
Kunststoff	T3020	= T1020
Kunststoff	T3030	= T1030
Kunststoff	T3050	= T1050
Titan	T2017	= T1017
Titan	T2018	= T1018
Titan	T2012	= T5215
Titan	T2019	= T5212
Titan	T2011	= T5211
Zirkon	T4000	= T10005 / T5005
Zirkon	T4001	= T10004 / T5004
Zirkon	T4002	= T10008 / T5008
Zirkon	T4003	= T10003 / T5003
Zirkon		= T3225
Zirkon Standard	T4006	= T3231
Zirkon Standard	T4005	= T3232
Zirkon Standard	T4007	= T3236

T4213

T5216

T5219

T5213

T5020

T4316

T4322

T4330